

## **VEGAFLEX 80 two-wire Foundation Fieldbus**

HW version, available since	Description
1.0.3	Modifications compared to HW version 1.0.2:
06/2023	- Update of the HF signal generation due to discontinued components
1.0.2	Modifications compared to HW version 1.0.1:
05/2019	<ul> <li>Cause for the failure of individual instruments with error message F040/8000</li> <li>"Failure in the electronics" due to too low signal amplitude</li> </ul>
	<ul> <li>Adaptation of the filter damping to increase the signal amplitude</li> </ul>
1.0.1	Modifications compared to HW version 1.0.0:
09/2015	<ul> <li>Cause for the failure of individual instruments with error message F040/8000</li> <li>"Failure in the electronics" with temperatures &lt; -2 °C removed</li> <li>Improved timing when synchronizing the HF signals</li> </ul>

## Legend:

Name	Description
HW version	Compatibility version.Function extension version.Error correction version
available since	Month/Year