

## VEGAFLEX 80 two-wire 4 ... 20 mA HART

HW version, available since	Description
1.1.3	Modifications compared to HW version 1.1.2:
06/2023	<ul> <li>Update of the HF signal generation due to discontinued components</li> </ul>
1.1.2	Modifications compared to HW version 1.1.1:
05/2019	<ul> <li>Cause for the failure of individual instruments with error message F040/8000</li> <li>"Failure in the electronics" due to too low signal amplitude         <ul> <li>Adaptation of the filter damping to increase the signal amplitude</li> </ul> </li> </ul>
1.1.1	Modifications compared to HW version 1.1.0:
09/2015	<ul> <li>Cause for the failure of individual instruments with error message F040/8000</li> <li>"Failure in the electronics" with temperatures &lt; -2 °C removed</li> <li>Improved timing when synchronizing the HF signals</li> </ul>
1.1.0	Modifications compared to HW version 1.0.0:
05/2014	<ul> <li>Improved EMC behaviour (burst coupling) with</li> <li>Transmission of the digital data of the current output</li> <li>Reset of processor</li> </ul>

## Legend:

Name	Description
HW version	Compatibility version. Function extension version. Error correction version
available since	Month/Year