Service info plics® hardware versions



VEGAFLEX 80 four-wire Modbus

HW version, available since	Description
1.0.2	Modifications compared to HW version 1.0.1:
06/2023	 Update of the HF signal generation due to discontinued components
1.0.1	Modifications compared to HW version 1.0.0:
05/2019	 Cause for the failure of individual instruments with error message F040/8000 "Failure in the electronics" due to too low signal amplitude Adaptation of the filter damping to increase the signal amplitude

Legend:

Name	Description
HW version	Compatibility version. Function extension version. Error correction version
available since	Month/Year

3. November 2023