VEGA

VEGAFLEX 80 HART

HW version, available since	Description
1.1.1 **09/2015**	**Modifications compared to HW version 1.1.0:** − Cause for the failure of individual instruments with error message F040/8000 "Failure in the electronics" with temperatures < -2 °C removed o Improved timing when synchronizing the HF signals

1.1.0
05/2014
	Modifications compared to HW version 1.0.0:
	− Improved EMC behaviour (burst coupling) with
	    o Transmission of the digital data of the current output
	    o Reset of processor

Legend:

Name	Description
HW version	Compatibility version.Function extension version.Error correction version
available since	Month/Year