

#### Reliable


Reliable monitoring of belt loading

#### **Cost effective**

Optimal equipment operation

#### **User friendly**

Simple external installation



### Sludge drying

# Measurement of belt loading and mass flow in a thermal sludge drying facility

Through drying, the weight and volume of the sludge is further reduced. In the thermal drying unit, which is equipped with a belt drier and a hot (+80 to +130 °C) air stream, water is removed from the sludge through evaporation. The continuous monitoring of belt loading is done by means of radiometric, i.e. radiation-based, measurement - this technique allows optimal, cost-effective dryer control.

#### More details



#### MiniTrac 31

Continuous monitoring of belt charging

- Non-contact measurement of the sludge level in the dryer
- Simple retrofitting during operation
- Optimal, cost-effective dryer control

#### **Show Product**



#### **VEGASOURCE 31**

Source holder with locking mechanism

- Reliable shielding allows use without control area
- Small footprint and easy installation
- Operational reliability through pneumatic on and off switching

#### **Show Product**



#### **VEGAMET 861**

Controller for powering the sensor, processing and displaying the measured values

- Clear, easy-to-read, user programmable display
- Robust housing designed for the harsh conditions in the field
- Universal controller for water and wastewater applications

### **Show Product**



# MiniTrac 31 Show Product



Measuring range - Distance

-

Process temperature

-40 ... 60 °C

Process pressure

Accuracy 0.1 %

Materials, wetted parts

No wetted material

Seal material

no media contact

Housing material

Aluminium

Stainless steel (precision casting)

Protection rating

IP66/IP67

Output

Profibus PA

Foundation Fieldbus

Four-wire: 4 ... 20 mA/HART

Ambient temperature

-40 ... 60 °C

# VEGASOURCE 31 Show Product



Ambient temperature

-20 ... 80 °C

### VEGAMET 861 Show Product



**Protection rating** 

IP66/IP67, Type 4X

Input

1 x 4 ... 20 mA/HART sensor input 2x digital input

Output

1 x 0/4 ... 20 mA current output 1x failure relay (instead of operating relay)

4x operating relay

Ambient temperature

-40 ... 60 °C

Measured value memory

Internally

SD card

